










Call me Bob.



JP400

JP512C

B3

U12C

3.3V

L1 6.8uH

CHARGE: OK ++

CHARGE +5V- +BAT-

U3

D1

IRF7333

U1

RP2040

U2

3.3V

5V

GND

3.3V

5V

GND

3.3V

5V

GND

3.3V

5V

GND

3.3V

5V

GND

3.3V

5V

GND

3.3V

5V

GND

3.3V

5V

GND

JP1

JP2

JP2

JP2

JP2

JP2

JP2

JP2

JP2

JP2

JP2

JP2