

**IBM Personal Computer AT[®]
Model 339**

**Supplement
for the
Hardware Maintenance Service**

March 18, 1986

Document Number 6280139

SS34-0001-00

© Copyright International Business Machines Corporation 1986

Instructions

This supplement package contains both replacement pages and supplemental pages. As you insert replacement pages, compare the date of each page to the page you are replacing. Keep the pages with the latest date. If the page in your manual is not dated, replace it.

- Turn to the AT¹ section of your manual. Replace the following sections with the sections from this package.
 - Jumpers and Switch Settings
 - Parts Catalog

Note: Do not replace the "Parts Supplement" or "Switch Supplement" in your manual.

- Turn to the DIAGNOSTIC MAPs section of your manual.
- Replace the following MAPs with the MAPs from this package.
 - MAP 0100: System Board (AT)
 - MAP 0200: Memory (AT)
 - MAP 0300: Keyboard (AT)

¹ Trademark of IBM

